REMARKS

Thorough examination and careful review of the application by the Examinor is noted and appreciated.

Claims 17-20 have been withdrawn from further consideration by the Examiner.

Claim Rejections Under 35 USC §102

Claims 15 and 16 are rejected under 35 USC \$102(b) as being anticipated by Rostoker 5,767,580. It is contended that Rostoker shows in Fig. 7d a multiplicity of contacts 750 on an TC chip which have a height less than one half of their diameter and are thus in a flattened homispherical shape.

The rejection of claims 15 and 16 under 35 USC \$102(b) based on Rostoker is respectfully traversed.

Claim 15 of the present invention narrowly recites a structure of an IC chip that has:

"a multiplicity of bond pads formed on said active surface, and

a multiplicity of solder bumps formed in flattened hemispherical shape on said multiplicity of bond pads, each of said multiplicity of solder bumps having a height less than '2 of the maximum diameter of said hemi-spherical shapes".

The Applicants respectfully submit that the solder bump of Rostoker is not formed on an active surface of an IC chip. Secondly, Rostoker does not show a multiplicity of bond pads that are formed on an active surface of an IC chip. Thirdly, Rostoker does not show a multiplicity of solder bumps formed on the multiplicity of bond pads. Fourthly, Rostoker does not teach solder bumps that have a height less than 4 of the maximum diameter of hemi-spherical shape.

Rostoker, at col. 12, lines 13-33 merely discloses: "Fig. 7d is a cross-sectional view A-A' of an assembly 700d of a conventional convex conductive bump contact 750 on a substrate 760 resting on the conductive contact structure 720 (which is disposed on another substrate, not shown)".

There is no mentioning of the fact that the solder bump is formed on a bond pad at all, there is no mentioning of a multiplicity of bond pads, there is no mentioning of an active surface of an IC chip on which the bond pads are formed, and there is no specific teaching that the solder bumps have a height less than ½ of the maximum diameter of the hemi-spherical shape of the solder bump.

The Applicants respectfully submit that the present invention claims 15 and 16 are clearly not anticipated by Rostoker '580 since Rostoker '580 clearly does not teach all the essential elements of the present invention, as recited in independent claim 15 and dependent claim 16.

The rejection of claims 15 and 16 under 35 USC \$102(b) based on Rostoker is respectfully traversed. A reconsideration for allowance of claims 15 and 16 is respectfully requested of the Examiner.

Based on the foregoing, the Applicants respectfully submit that all of the pending claims, i.e. claims 15 and 16, are now in condition for allowance. Such favorable action by the Examiner at an early date is respectfully solicited.

Respectfully submitted,

/Tung & Associates

Randy W. Tung Reg. No. 31,311

Telephone: (248) 540-4040